


# 2FT EuroFit Steel Base Display

## Product Parts

- 1 - Corners (x2)
- 2 - Bottom Pole (x2)
- 3 - Fabric Graphic (x1)
- 4 - Vertical Shock Cord Pole (x2)
- 5 - Horizontal Middle Pole (x1)
- 6 - Base (x1)




## Display Set-Up

### Step 1

Begin by removing all parts from the carry case and place on a clean, flat surface.


### Step 3

Screw the bottoms (2) into the Base (6) Clockwise until snug. \* DO NOT OVER TIGHTEN




### Step 5

Attach the Corners (1) to the Vertical Shock-Corded Poles (4) as shown.




### Step 2

Assemble all poles including the Bottom Poles by placing the tapered end of one pole into the large end of the next while pressing the snap button as shown.




### Step 4

Insert the ends of the Horizontal Middle Pole (5) into both sides of the Vertical Shock-Corded Poles (4) as shown.



### Step 6

Slide Graphic (3) over the top of the display as shown.



## Storage & Care

Place all product parts into Carry Case and store in a cool dry location. Recommended for indoor use only. Machine wash on gentle cycle using mild detergent. Tumble Dry No Heat. Do NOT dry clean, Do NOT Iron.